



Service Bulletin

SB 81440-XX-00-23

2101 I/O Approach Plus GPS Navigation Systems, Part Numbers 81440-02-XXXX, 81440-03-XXXX, 81440-12-XXXX, 81440-32-XXXX, 81440-33-XXXX, and 81440-42-XXXX.

Release of operating system –241M.

SUMMARY: FreeFlight Systems has released software system –241M for the 2101 I/O Plus.

I. PLANNING INFORMATION

A. Effectivity

This Service Bulletin applies to the 2101 I/O Approach Plus GPS Navigators, Part Numbers 81440-02-XXXX, 81440-03-XXXX, 81440-12-XXXX, 81440-32-XXXX, 81440-33-XXXX, and 81440-42-XXXX, where XXXX equals the system operating software.

Installation of software version -241M will become mandatory. Continued IFR operations after June/2009 will require software version -241M and its support of 4 MB Nav data bases.

Installation of software version -241M also requires implementation of hardware service bulletin 81440-XX-34-14.

B. Reason

This Service Bulletin includes the corrections previously incorporated in SB 81440-XX-00-19, software version 241J, and therefore, meets the terminating requirements of AD 2009-05-08.

This Service Bulletin advises all users of 2101 I/O Approach Plus Navigators, Part Numbers 81440-02-XXXX, 81440-03-XXXX, 81440-12-XXXX, 81440-32-XXXX, 81440-33-XXXX, and 81440-42-XXXX, of the availability of a revised operating system, -241M.

The following changes have been incorporated into software version –241M:

- Fixed display of the estimated GPS accuracy, required for oceanic/remote operations.

C. Description

Operating system –241M is loaded using a FLASH EDGE card.

D. Approval

Operating software version –241M is a minor modification to version –241L, which was previously approved under TSO C129 (A1). 2101 I/O installations that have been FAA approved with software programs other than –241x must be re-evaluated when software version –241M is installed.

E. Manpower

The following man-hour estimates are based on incorporation concurrent with an unscheduled repair or during routine maintenance:

Units	Compliance	Man Hours
All RDUs	During Routine Maintenance	0.5
All RDUs	During Repair	0.5

F. Weight and Balance

None

G. Electrical Load Data

Not Affected

H. Reference

ECN S08013

I. Other Publications Affected

- 84923, Rev B FreeFlight 2101 I/O Approach Plus Pilot Guide Supplement
- 84929, Rev B FreeFlight 2101 I/O Approach Plus GPS Receiver Installation and Checkout Manual Supplement

J. Interchangeability and Identification

Modified and unmodified units are not interchangeable.

2101 I/O Approach Plus GPS Navigation Systems having operating system –241M shall be identifiable by the identification label on the top of the unit, bearing part number 81440-XX-241M.

II. MATERIAL INFORMATION

A. Price and Availability

Call FreeFlight Systems for price and availability at time of purchase.

All operators will be charged a \$300 media/handling fee for each PCMCIA card shipped. Operators who return a serviceable card within 90 days will receive credit. Observe handling precautions with each card to ensure reasonable protection of the card (normal wear and tear is acceptable). The fee will be due and payable for cards that are not returned and for cards returned in unserviceable condition. Return cards to FreeFlight Systems, Attention Sales Department (see address below), to receive credit.

Customers have two choices. They may elect to send Navigators to the FreeFlight Factory Service Center; or they may send units to an authorized Level II Service Center for installation of this software upgrade.

Modifications accomplished at the Factory Service Center will be completed within fifteen (15) working days after receipt of the unit, depending upon parts availability.

Level II Service Centers wishing to incorporate Service Bulletin 81440-XX-00-23 should issue a purchase order to FreeFlight for the number of Service Bulletin kits required.

B. Parts List

Service Bulletin Kit 81440-XX-00-23 contains:

FreeFlight PN	Qty	Nomenclature	Notes
82998-241M	1	Flash Card loaded with 2101 I/O Plus operating system v. -241M	1
81461-XX	1	4 megabyte database	2
81941	1	Part Number Identification Label	
SB 81440-XX-00-23	1	Service Bulletin Document (this document)	
84923, Rev B	1	FreeFlight 2101 I/O Approach Plus Pilot Guide Supplement	
84929, Rev B	1	FreeFlight 2101 I/O Approach Plus GPS Receiver Installation and Checkout Manual Supplement	

Note 1: An invoice for \$300 for the flash card will accompany the Service Bulletin kit. Operators who return an undamaged flash card within 90 days to FreeFlight Systems, Attention Sales Department (see address below), will receive credit.

Note 2: Please state which database is required, North America (81461-10), Eurasia (81461-12), or Pacific South America (81461-13).

C. Ordering Information

Operators of the 2101 I/O Approach Plus wishing to upgrade their system may send the unit(s) to an approved Level II Service Center or the FreeFlight Factory Service Center.

To upgrade the operating system at a Level II Service Center, send a purchase order requesting Service Bulletin kit P/N 81440-XX-00-23 to:

FreeFlight Systems	Attn.: Sales Dept.
3700 Interstate 35 S.	Telephone 1 (254) 662-0000
Waco, TX 76706 USA	Fax 1 (254) 662-9451

For FreeFlight Factory Service Center modification, send the Navigator and a purchase order requesting incorporation of Service Bulletin 81440-XX-00-23 to:

FreeFlight Systems
3700 Interstate 35 S.
Waco, TX 76706 USA

Attn.: Repair Dept.
Telephone 1 (254) 662-0000
Fax 1 (254) 662-9452

D. Warranty

This Service Bulletin does not affect the standard warranty of the unit from date of purchase. For units out of warranty, this modification will be covered for ninety (90) days.

III. ACCOMPLISHMENT INSTRUCTIONS

A. Record Configuration Settings

Software loading will erase the installation settings and the user settings. Therefore, it is important to record these settings before installing the revised software. For information about installation settings, refer to the *2101 I/O Approach Plus GPS Navigation System Installation and Checkout Manual*, PN 82882 (Section III - Checkout). Following the instructions, access the Installation Set Up submenu.

1. Record the configuration settings on the Configuration Record Sheet found in Section III of the manual.
2. Turn unit off.

Two sets of loading instructions follow. The instructions in Section III.B are for loading version -241M over version -241B, 241C, -241D, -241E, 241F, 241G, 241H, 241J, 241K or 241L. The instructions in Section III.C are for loading version -241M over versions -0241 or -241A.

B. Instructions for Updating the 2101 I/O Approach Plus Operating System from Version -241B, -241C, -241D, -241E, -241F, -241G, -241H, -241J or 241K.

1. Inspect the provided flash card, P/N 82998-241M, and verify that it contains the following text on the label:

FreeFlight Systems
PN 82998-241M
SYSTEM: 241M
NIOP: 2.831
CRC: 5966-8B71
AIO: 0121
CRC: EEF4-E834
GPS: 5.05-1208
CRC: B72A-A2D5
Not A Jeppesen
Database Card

2. Insert the flash card into the memory card slot on the front of the unit.
3. Turn power ON to the 2101 I/O Plus. The unit will begin its startup procedure.
4. Verify that the following message is displayed:

FLASH CARD DETECTED

AVAILABLE VERSIONS:

It will be followed by:

NAV: 2.831 59668B71
PUSH NAV TO CONTINUE

5. Verify that the software version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

6. Press **NAV**. The following message will appear.

GPS: 5.05B B72AA2D5
PUSH NAV TO CONTINUE

7. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

8. Press **NAV**. The following message will appear.

AIO: 1.21 EEF4E834
PUSH NAV TO CONTINUE

9. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

10. Press **NAV**.

11. Verify that the following messages are displayed. A pattern will scroll across the bottom line of the display to indicate that the image verification process is taking place.

VERIFYING IOP IMAGE
VERIFYING GPS IMAGE
VERIFYING AIO IMAGE

After successful image verification, the following message will appear:

FLASHCARD IOP, AIO
AND GPS IMAGES OK

A message quickly flashes by and then the following appears.

UPDATE GPS CARD NOW?
NAV = YES AUX = NO

12. Press **NAV**. The following message will appear.

UPDATING GPS FLASH

It is followed by:

GPS FLASH UPDATE OK
PRESS NAV TO CONT

13. Press **NAV**. The following message will appear.

UPDATE AIO UNIT NOW?
NAV = YES AUX = NO

14. Press **NAV**. The following message will appear.

UPDATING AIO FLASH

It is followed by:

AIO FLASH UPDATE OK
PUSH NAV TO CONT

15. Press **NAV**. The following message will appear.

UPDATE NAV IOP NOW?
NAV=YES AUX=NO

16. Press **NAV**. The following message will appear.

UPDATING IOP FLASH

After the image verification is complete, the unit will reset. Then it will display this message:

PERFORMING BUILT IN
TEST
CLEAR BATTERY BACKED
MEMORY SUCCESSFUL
FreeFlight
2101 I/O SAR
SYSTEM CODE: 241M
c2008

It is followed by:

IOP ROM UPDATED OK
PWR OFF, REMOVE CARD

17. Turn the unit OFF. Remove the flash card from the memory card slot and insert a 4 MB database card.
18. Turn the power ON.
19. Verify the following message on the display:

SYSTEM CODE: 241M
c2008

After the database validation is complete, observe the following scroll up the screen.

NAV Computer --OK
GPS Computer --OK
Aux IO Computer --OK
Database --OK

or

Database Expired

Ready for Navigation
Select any mode

20. Press AUX until the SYSTEM STATUS screen is displayed.
21. Rotate the small knob clockwise until the following screen is displayed:
REVISION: NAV 2.831
GPS 5.05-1208 AIO0121
22. Verify that the NAV IOP software version matches the line above.
23. Rotate the small knob clockwise one click and verify that the following line is displayed:
SYSTEM CODE: 241M
c2008
24. Press the MSG key and check for any of the following error messages.
GPS CONFIG INVALID
IFR NOT ALLOWED
AIO CONFIG INVALID
IFR NOT ALLOWED
S/W CONFIG INVALID
IFR NOT ALLOWED
25. If any of the above messages appear, perform the software loading again. If there are still error messages after the second attempt, call FreeFlight.
26. Updating the 2101 I/O Approach Plus to operating system version -241M from version -241B, -241C, -241D, -241E, -241F, -241G, 241H, 241J, 241K or 241L is complete. Go to Section D, Identification.

C. Instructions for Upgrading the 2101 I/O Approach Plus Operating System to Version -241M from Version -0241 or -241A

**IMPORTANT NOTES
PLEASE READ AND FOLLOW CAREFULLY**

The software **MUST** be loaded in the correct order, as described in the instructions immediately following this box. The loading options on the 2101 I/O Plus display will not be presented in that order. Therefore, take care to follow the loading directions in this Service Bulletin **EXACTLY IN SEQUENCE AS WRITTEN**.

DO NOT cycle power during the loading process except where noted in the instructions. Cycling power during software loading will damage the unit. If this occurs, the unit must be returned to FreeFlight for repair.

1. Inspect the provided flash card, P/N 82998-241M, and verify that it contains the following text:

FreeFlight Systems
PN 82998-241M
SYSTEM: 241M
NIOP: 2.831
CRC: 5966-8B71
AIO: 0121
CRC: EEF4-E834
GPS: 5.05-1208
CRC: B72A-A2D5
Not A Jeppesen
Database Card

2. Insert the flash card into the memory card slot on the front of the unit.
3. Turn power ON to the 2101 IO Plus. The unit will begin its startup procedure.
4. Verify that the following message is displayed:

FLASH CARD DETECTED
AVAILABLE VERSIONS:

It is followed by:

NAV: 2.831 59668B71
PUSH NAV TO CONTINUE

5. Verify that the software version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.
6. Press **NAV**. The following message will appear.

GPS: 5.05B B72AA2D5
PUSH NAV TO CONTINUE

7. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

8. Press **NAV**. The following message will appear.

AIO: 1.21 EEF4E834
PUSH NAV TO CONTINUE

9. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

10. Press **NAV**.

11. Verify that the following messages are displayed. A pattern will scroll across the bottom line of the display to indicate that the image verification process is taking place.

VERIFYING IOP IMAGE
VERIFYING GPS IMAGE
VERIFYING AIO IMAGE

After successful image verification, the following message will appear:

FLASHCARD IOP, AIO
AND GPS IMAGES OK

A message quickly flashes by and then the following appears.

UPDATE GPS CARD NOW?
NAV = YES AUX = NO

12. Press **AUX**. (If you make a mistake and press NAV, cycle power and start over.)

13. Then the following message is displayed.

UPDATE AIO UNIT NOW?
NAV = YES AUX = NO

14. Press **NAV**. The following message appears:

UPDATING AIO FLASH

It is followed by:

AIO IMAGE VERIFICATION OK
PRESS NAV TO CONT

15. Press **NAV**. The following message appears:

UPDATE NAV IOP NOW?
NAV = YES AUX = NO

16. Press **NAV**. The following message will appear.

UPDATING IOP FLASH

After the image verification is complete, the unit will reset and then display this message:

PERFORMING BUILT IN TEST
CLEAR BATTERY BACKED
MEMORY SUCCESSFUL

The unit will go through the startup sequence. (The following display will appear if version -241M is being loaded over -241A, but not if it is being loaded over -0241. **DO NOT REMOVE THE CARD!**)

IOP ROM UPDATED OK
PWR OFF, REMOVE CARD

17. Turn OFF power to the 2101 I/O Plus. Wait 30 seconds. Turn ON power to the unit.

18. Verify that the following message is displayed:

PERFORMING BUILT IN TEST

Then the unit will reset. Afterward it will display:

FreeFlight
2101 I/O SAR

SYSTEM CODE: 241M
c2008

FLASH CARD DETECTED
AVAILABLE VERSIONS:

This is followed by:

NAV: 2.831 59668B71
PUSH NAV TO CONTINUE

19. Verify that the software version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

20. Press **NAV**. The following message will appear.

GPS: 5.05B B72AA2D5
PUSH NAV TO CONTINUE

21. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

22. Press **NAV**. The following message will appear.

AIO: 1.21 EE4E834
PUSH NAV TO CONTINUE

23. Verify that the Software Version and CRC on the top line of the display match the above text. If not, then terminate the programming procedure immediately and contact FreeFlight.

24. Press **NAV**.

25. Verify that the following messages are displayed:

VERIFYING IOP IMAGE

VERIFYING GPS IMAGE

VERIFYING AIO IMAGE

After successful image verification, the following message will appear:

FLASHCARD IOP, AIO
AND GPS IMAGES OK

A message quickly flashes by and then the following appears:

UPDATE GPS CARD NOW?
NAV = YES AUX = NO

26. Press **NAV**. The following message will be displayed:

UPDATING GPS FLASH

It is followed by:

GPS IMAGE VERIFICATION OK
PUSH NAV TO CONT

27. Press **NAV**. The following message will be displayed:

UPDATE AIO UNIT NOW?
NAV = YES AUX = NO

28. Press **NAV**. The following message will be displayed:

UPDATING AIO FLASH

It is followed by:

AIO IMAGE VERIFICATION OK
PUSH NAV TO CONT

29. Press **NAV**. The following message will be displayed:

UPDATE NAV IOP NOW?
NAV = YES AUX = NO

30. Press **NAV**. The following message will be displayed:

UPDATING IOP FLASH

After the flash update is complete, the unit will reset. Then it will display this message:

PERFORMING BUILT IN TEST
CLEAR BATTERY BACKED
MEMORY SUCCESSFUL

The unit will reset. Then the following message will be displayed:

IOP ROM UPDATED OK
PWR OFF, REMOVE CARD

31. Turn the unit OFF. Remove the flash card from the memory card slot and insert a 4 MB database card.

32. Turn the power ON. The unit will display this message:

PERFORMING BUILT IN TEST

Then the unit will reset.

33. Verify the following message on the display:

SYSTEM CODE: 241M
c2008

34. After the Database validation is complete, observe the following scroll up the screen.

NAV Computer	--OK
GPS Computer	--OK
Aux IO Computer	--OK
Database	--OK
or	
Database	Expired

Ready for Navigation
Select any mode

35. Press AUX until the SYSTEM STATUS screen is displayed.
36. Rotate the small knob clockwise until the following screen is displayed:

REVISION: NAV 2.831
GPS 5.05-1208 AIO0121

37. Verify that the NAV IOP software version matches the line above.
38. Rotate the small knob clockwise one click and verify that the following line is displayed:

SYSTEM CODE: 241M
c2008

39. Press the MSG key and check for any of the following error messages.

GPS CONFIG INVALID
IFR NOT ALLOWED
AIO CONFIG INVALID
IFR NOT ALLOWED
S/W CONFIG INVALID
IFR NOT ALLOWED

If any of the above messages appear, perform the software loading again. If there are still error messages after the second attempt, call FreeFlight.

D. Identification

When the software has been successfully loaded with no errors reported, the flash update procedure is complete and the operating software is version -241M. Remove the old identification label on the top of the unit and replace it with the Part Number Identification Tag (PN 81941) that was provided in the Service Bulletin kit.

E. Perform System Reset

NAVIGATOR RESET

Upon completion of this procedure, the unit will be in "cold start" mode.
Please allow up to 15 minutes for GPS acquisition.

Memory Reset –

1. With UUT turned OFF, simultaneously press and hold the following keys:
NAV, NRST and -D>
2. Turn UUT power ON and continue holding the keys above until the following message appears:
CLEAR BATTERY BACKED
MEMORY SUCCESSFUL
3. Release the keys.
4. Turn the UUT power OFF.
5. Turn the UUT power ON. Monitor the display and verify message from Step 2 above.

End of Reset Procedure

F. Restore Configuration Settings

Restore the configuration settings that were recorded prior to loading software. For installation settings, refer to the *2101 I/O Approach Plus GPS Navigation System Installation and Checkout Manual*, PN 82882 (Section III - Checkout). Instructions for accessing the user setup mode and configuring the settings are in the *2101 I/O Approach Plus GPS Navigator Pilot Guide*, PN 82881, Appendix C.