



## Service Information Letter

**SIL FFS09**

3700 IH 35 Waco, TX 76706 USA      PHONE: 1 (254) 662-0000      FAX: 1 (254) 662-9451

**TO:** Operators of FreeFlight Systems and Trimble GPS navigation systems, with 4MB NavData capability, using the following Jeppesen NavDatabases: DTRM55 and DTR550.

**FROM:** FreeFlight Systems Customer Support

**SUBJECT: Release of an alternate STAR selection procedure**

**PURPOSE:** There have been reports of system resets, similar to a power cycle, occurring with the selection of certain STAR's associated with the above databases.

The following procedure was developed to allow continued use of the affected STAR, until such time as a correction becomes available.

**ACTION:** When selecting a STAR, locate the desired transition, as you would normally but rather than performing a direct-to to the transition, perform the following operation;

- 1) Turn the outer knob CW one click, then press DIR, DIR to join the first leg of the STAR.
- 2) Go to the FPL page and press DIR.
- 3) Turn the outer knob CCW one click (to select direct-to the transition) and press DIR again.

This procedure provides the same result without the reset.

For Operators or Dealers who need additional information, please contact FreeFlight Systems Customer Support Department for assistance:

Telephone: (1) 254 662-0000

Fax: (1) 254 662-9451

**ORIGINAL:** January 19, 2011

**SIL FFS09**  
**PAGE 1 of 2**



Email: [Support@FreeFlightSystems.com](mailto:Support@FreeFlightSystems.com)

**PUBLICATIONS AFFECTED:**

Pilots Guides 83166 Rev. A Dated December 15, 1997 and later.

Pilots Guide 82877 Rev. E Dated September 22, 1998 and later.

Pilots Guide 83164 Rev. A Dated December 15, 1997 and later.

Pilots Guide 82897 Rev. F Dated June 21, 2002 and later.

Pilots Guide 83162 Rev. A Dated December 15, 1997 and later.

Pilots Guide 82881 Rev. G Dated May 31, 2006 and later.