



Service Information Letter

SIL FFS08

To: FreeFlight Systems (Trimble) Dealers, Service Centers and Customers
From: FreeFlight Systems (FFS) Customer Service

Subject: FreeFlight Systems announces release of software version “N”, offering enhanced operation on systems using the new 4MB NavData solution

We are pleased to announce the release of a new revision of several software versions, which will enhance the overall operation of systems running the 4MB NavData service.

Although this is an optional upgrade, FFS strongly encourages operators to incorporate the change, especially those using the larger North American data base. Without the “N” update, long computational delays in processing flight planning operations (such as direct-to) may be observed.

The matrix below shows the SB number and S/W version, for each specific model of approved GPS Navigation System.

Service Bulletin Number	Software Version & Revision	Applicable equipment
SB 81440-XX-00-25	241N	FreeFlight/Trimble 2101 I/O Approach Plus
SB 81440-XX-00-24	243N	Trimble 2101 I/O Approach
SB 81439-XX-00-15	240N	FreeFlight/Trimble 2101 Approach Plus
SB 81439-XX-00-16	242N	Trimble 2101 Approach
SB 81438-XX-00-16	240N	Trimble 2000 Approach Plus
SB 81438-XX-00-17	242N	Trimble 2000 Approach

Please contact FreeFlight Systems to order the applicable Service Bulletins or for additional information.

FreeFlight Systems
3700 Interstate 35 South
Waco, Texas 76706-3756 U.S.A.
Toll Free (US only); 1 (800) 487-4662
Telephone number; 1 (254) 662-0000
Fax number; 1 (254) 662-9452
Email; Support@freeflightsystems.com
www.FreeFlightSystems.com